


# Clean sweep

Preventing plastic from being released into the environment is a mindset. Everyone, every sector of the industry - resin producers, transporters, bulk terminal operators or plastic processors - play a role in reducing pellets, flake, and powder leakage. It's the little things that count. They all add up when you consider the thousands of facilities in the industry and the frequency with which pellets, flakes, and powders are loaded and unloaded. Involvement of everyone in every company, from management to employees in the workplace, is essential for reducing plastics in the environment.



## What can you do as a driver?

- Prevent spillage of plastic pellets and powders. Always follow instructions and check your vehicle and all attachments before, during and after loading/unloading.
- In case of spillage, intervene immediately:
  - Stop loading/unloading immediately.
  - Report the problem to the company management and your planner.
  - Fix the cause and only then proceed.
- Clean up the spill quickly and effectively.
  - Clean the manholes, spouts, mudguards, bumper, chassis etc.
  - Clean up all spillage around the truck with brush and dustpan.
- Dispose of plastic granules and powders appropriately.
  - Ask the loading/unloading site where you can leave the spilled product.